

Schattenbaum PCA Intro to D/E  
January 16, 2008

Grid Tech Inspection



Preparation is essential to ensure a *safe*, enjoyable day at a Schattenbaum or any other PCA Region D/E Event. When you receive your acceptance notice print it out and refer to it often. Schedules, assignments and most importantly lunch will be listed. Arrival time at the track is generally 7am.

Upon arriving at the track secure a parking space and empty your vehicle. Any loose items can present a problem once you are on the track. Be sure to check under the seats and visors. Radar detectors and E-Z Pass tags should be removed. After the car is empty prepare yourself and your car for Grid Tech. Have all paperwork filled out and signed. Bring your helmet. All wheel nuts/lugs should be in place and properly torqued. Tire pressures and fluid levels should be checked. Affix your numbers. Once you are ready bring your car up for Grid Tech.

The Schattenbaum Tech Team will be taking your completed and signed tech form. We will be looking over your car and talking with you. Our philosophy is to provide a check of your car and *you*. Most importantly be ready for some safe, serious fun.

Remember you must go through registration also. For all Schattenbaum events Registration and Grid Tech are independent but you *must* complete both prior to the morning Drivers Meeting.